

**GUJARAT TECHNOLOGICAL UNIVERSITY**  
**BE - SEMESTER-VII EXAMINATION – WINTER 2015**

**Subject Code: 170902****Date: 07/12/2015****Subject Name: Electrical Machine Design – I****Time: 10:30am to 1:00pm****Total Marks: 70****Instructions:**

1. Attempt all questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.

- Q.1** (a) Explain various factors affecting selection of number of poles for D.C. machine. **07**  
 (b) Explain how following factors influence the main dimensions of a D.C. machine. **07**  
 (1)  $L/\zeta$  ratio,  
 (2) Peripheral speed,  
 (3) Moment of inertia,  
 (4) Voltage between adjacent segments.

- Q.2** (a) Explain guidelines used for the selection of number of armature slots in D.C. machine design. **07**  
 (b) Determine the main dimensions, number of poles and length of air gap of a 600 kW, 500 V, 900 rpm generator. Assume average gap density as  $0.6 \text{ Wb/m}^2$  and ampere conductors per metre as 35000. The ratio of pole arc to pole pitch is 0.75 and efficiency is 91 percent. **07**  
 The following are the design constraints: peripheral speed:  $\leq 40 \text{ m/s}$ , frequency of flux reversals:  $\leq 50 \text{ Hz}$ , current per brush arm:  $\leq 400 \text{ A}$  and armature mmf per pole  $\leq 7500 \text{ A}$ .  
 The mmf required for air gap is 50 percent of armature mmf and gap contraction factor is 1.15.

**OR**

- (b) Write short note on classification of insulating materials. **07**  
**Q.3** (a) Discuss factors to be considered while deciding the length of air gap in the design of a D.C. machine. **07**  
 (b) Explain diff. methods used to improve armature reaction effect in dc machine. **07**

**OR**

- Q.3** (a) Briefly explain cooling methods of transformer. **07**  
 (b) Explain effect of change in frequency on losses, voltage & leakage impedance of transformer. **07**  
**Q.4** (a) What is design optimization? Derive necessary condition for designing a transformer with minimum cost. **07**  
 (b) Explain : **07**  
 a. Significance of mitered joints in transformer.  
 b. Design difference between power & distribution transformer.

**OR**

- Q.4** (a) Derive equation  $E_t = k \sqrt{Q}$  where  $Q = \text{kVA rating of a transformer}$ . **07**  
 Explain how service condition of transformer affect the value of  $K$ .  
 (b) Determine the main core & yoke dimensions for a 200 KVA, 50 Hz, 1-phase core type transformer. **07**  
 Window space factor = 0.32 Current density =  $3 \text{ A/mm}^2$   
 Max. flux density =  $1.1 \text{ Wb/m}^2$  Volts per turn = 14 V  
 Stacking factor = 0.9 Net iron area =  $0.56 \cdot d^2$   
 Cruciform core with distance between adjacent limbs = 1.6 times width of core

- Q.5 (a)** Define specific electric and specific magnetic loading. Also state advantage and disadvantages of these loadings. **07**
- (b)** Estimate the per unit regulation, at full load and 0.8 power factor lagging, for a 300 kVA, 50 Hz, 6600/400 V, 3 phase, delta/star, core type transformer. The data given is: **07**
- H.V. winding: outside diameter=0.36m, inside diameter=0.29m, area of conductor=5.4mm<sup>2</sup>
- L.V. winding: outside diameter=0.26m, inside diameter=0.22m, area of conductor=170mm<sup>2</sup>
- Length of coils=0.5 m, voltage per turn=8V, resistivity=0.21 Ω/m/ mm<sup>2</sup>.
- OR**
- Q.5 (a)** Briefly explain the principles of core design of a current transformer. **07**
- (b)** What is window space factor? Explain how it varies with (1) KVA rating (2) KV rating **07**

\*\*\*\*\*