

GUJARAT TECHNOLOGICAL UNIVERSITY
PDDC - SEMESTER-II EXAMINATION – SUMMER 2016

Subject Code: X21101**Date: 31/05/2016****Subject Name: ELECTRICAL ENGINEERING****Time: 10:30 AM to 01:00 PM****Total Marks: 70****Instructions:**

1. Attempt all questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.

- Q.1** (a) Explain the types of d.c. generators. **07**
(b) Derive the equation of armature torque of a d.c. motor. **07**
- Q.2** (a) Explain the construction features and working principle of 1-phase transformer. **07**
(b) Explain torque-slip characteristics of 3-phase induction motors. **07**
- OR**
- (b) Explain working principle of 3-phase induction motor. Write types of 3-phase induction motors. **07**
- Q.3** (a) Why starter is necessary for d.c. motors ? Explain three point starter. **07**
(b) Explain the characteristics of d.c. shunt and series motors. **07**
- OR**
- Q.3** (a) What is the voltage regulation of alternator ? Explain synchronous impedance method for voltage regulation. **07**
(b) Explain equivalent circuit of 1-phase transformer. **07**
- Q.4** (a) Explain the methods of speed control of d.c. shunt motors. **07**
(b) A 4 pole, d.c. motor take a 50 A armature current. The armature has lap connected 480 conductors. The flux per pole is 20 mWb. Calculate the gross torque developed by the armature of the motor. **07**
- OR**
- Q.4** (a) Explain construction and working principle of repulsion motor. **07**
(b) Explain construction and working principle of permanent magnet motor. **07**
- Q.5** (a) Explain specifications of stepper motor and its applications. **07**
(b) Explain construction features and working principle of synchronous motor. Also write its applications. **07**
- OR**
- Q.5** (a) Explain construction and working of AC servomotors. **07**
(b) A 4 pole, 3-phase, 50 Hz, star connected induction motor has a full load slip of 4 %. Calculate full load speed of the motor. **07**
